

BELZONA® RESTORES CORRODED PUMP HOUSING

CUSTOMER

Drinking water supplier, Lisbon region, Portugal

APPLICATION DATE

November 2004

APPLICATION SITUATION

Horizontal split case centrifugal water distribution pump.

PROBLEM

The pump had extensive corrosion.

PRODUCTS

Belzona® 1341 (Supermetalglide)

SUBSTRATE

Cast iron

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet CEP-5 & 10.

BELZONA FACTS

Another similar pump had been coated with Belzona 6 years previously and recent inspection found it to be excellent condition so client had no hesitation in specifying Belzona again.

PICTURES

1. Corroded pump housing.
2. Corroded pump outlet.
3. Application of Belzona® 1341.
4. Completed application.



www.belzona.com



Europe & Africa
Belzona Polymers Ltd.
Harrogate, UK
t: +44 1423 567641
f: +44 1423 505967
e: belzona@belzona.co.uk

The Americas
Belzona Inc.
Miami, FL USA
t: +1 (305) 594-4994
f: +1 (305) 599-1140
e: belzona@belzona.com

Canada
Belzona Canada Inc.
Richmond, ON Canada
t: +1 (905) 737-1515
f: +1 (905) 737-1597
e: belzonacanada@belzona.com

Asia & Oceania
Belzona Asia Pacific
Chonburi, Thailand
t: +66 38 491031
f: +66 38 491102
e: belzona@belzona.cn

China
Belzona Hong Kong
Hong Kong, China
t: +852 3753 7505
f: +852 3753 7510
e: belzona@belzona.hk

